



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

date, 2008

Supervisor LK

<b>Mine Name:</b> Mystery-ML 45848	<b>Permit Number:</b> S0190034
<b>Operator Name:</b> James Hill	<b>Inspection Date:</b> 05082008
<b>Inspector(s):</b> Tom Munson	<b>Time:</b> 10 AM
<b>Other Participants:</b> none	<b>Mine Status:</b> inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

As a new inspector to this area, this inspection was mainly to find the site and assess the amount of disturbance.

**Bond:** \$2,000 **Permit fees:** Current

#### Inspection Summary:

I tried to find this site and was unable to determine its location. I will contact Mr. Hill to have him take me to this location, the next time I do inspections in this area.

#### Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature

Thomas Munson

Tm:pb

cc: (OPERATOR)

willstokes@utah.gov

O:\M019-Grand\S0190034-Mystery\inspections\insp-S190034-05082008.doc